

-1-

Date: 10/23/01 Express Mail Label No. EV 044390534 US

Inventors: Hans Groeblacher and James W. Nixon
Attorney's Docket No.: 2309.2001-000

METHOD AND SYSTEM FOR DUAL CO-EXTRUSION

RELATED APPLICATION

This application claims the benefit of U.S. Provisional Application No. 60/267,987, filed on February 9, 2001, the entire teachings of the above application are
5 incorporated herein by reference.

BACKGROUND OF THE INVENTION

An extrusion such as extruded polyvinyl chloride (PVC) pipe is formed by feeding plastic into an extruder where it is subjected to high temperatures to create a molten substrate. The substrate then proceeds through a feed tube, at the end of which
10 additional material known as capstock can be applied if desired. The process of adding additional material to the substrate is known as co-extrusion. The substrate and capstock are known as melt. The melt proceeds through an extrusion head, at the end of which the melt passes through a die. The die contains the circular cross-sectional profile shape to be extruded. The melt hardens as it exits the die in the desired cross-
15 sectional form. The hardened material forms a tube that can grow to arbitrary length as additional melt is extruded.

Normally, PVC pipe is produced by extruding molten plastic through a single die of an extruder. In some cases, two PVC pipes are produced simultaneously by extruding molten plastic through a Y-block, a pair of extrusion heads and a pair of dies.

20 The ultimate shape of the extrusion is determined by a melt flow passage in the die between a bushing which surrounds a pin or mandrel. For circular pipe, the pin is

circular in cross-section and an opening in the bushing which surrounds the pin is circular. To obtain a non-circular cross-section, such as a square, a circular extrusion is typically reshaped through a transition bushing and pin which are circular at the inlet and square, for example, at the outlet.

5 SUMMARY OF THE INVENTION

In accordance with the invention, there is provided a system and method for co-extruding two simultaneous melts. A co-extrusion system contains a primary extruder, a secondary extruder, a primary flow director, a secondary flow director, at least first and second co-extrusion assemblies and extrusion dies. The primary flow director
10 divides the solid melt from the primary extruder into two symmetrical flow paths. The secondary flow director divides the melt from the secondary extruder into two symmetrical flow paths. The first and second co-extrusion assemblies co-extrude the melt simultaneously from the primary and secondary flow directors. The co-extrusion takes place ahead of the dies so that there is no substantial pressure change in the melt,
15 thereby providing for consistent and uniform flow control. The dies receive the co-extruded melt from their respective co-extrusion assemblies.

The secondary flow director contains top and bottom plates, each of which have channels which form two symmetrical flow paths. Conduits extend from the bottom plate to feed the melt into the co-extrusion assemblies.

20 BRIEF DESCRIPTION OF THE DRAWINGS

The foregoing and other objects, features and advantages of the invention will be apparent from the following more particular description of preferred embodiments of the invention, as illustrated in the accompanying drawings in which like reference characters refer to the same parts throughout the different views. The drawings are not
25 necessarily to scale, emphasis instead being placed upon illustrating the principles of the invention.

Figs. 1A-C show plan, side and perspective views of a dual co-extrusion set-up;

or another material used in the industry. The co-extrusion assembly 6 comprises the following components: capstock flow insert 20; adapter flange 22; horizontal plate 24; vertical plate 26; plate-to-block adapter 28; dual coex block 30; locating insert 32; co-extrusion pin 34; dual coex bushing 36; main flow insert 38; heat bands 42; heat plate covers 50; and thermal sensors 44.

To avoid redundancy, one half of the system will be described since the second half is a mirror image of the first. Solid substrate flows from the “Y” adapter 4 through the main flow chamber 48 (Fig. 5A) of the dual coex block 30. As shown in Figs. 2B and 3, the capstock flows from adapter flange 22 through horizontal plate 24, vertical plate 26 and plate-to-block adapter 28. As shown in Figs. 4A, 4B and 5A, the capstock is divided into two symmetrical flow paths by capstock divider 31 and facing channels 29 and 29' in the plate-to-block adapter 28 and dual coex block 30 respectively. The plate-to-block adapter 28 is curved to allow for continuous flow of the capstock through the divider without hitting an edge and burning the melt. The capstock then flows through the dual coex block 30 at coat hanger neck 33 (Fig 5A) at least at a 30 degree angle to allow the capstock to flow continuously into the coat hanger 35. In one embodiment, a 45 degree angle is used to minimize the length of the flow channel reducing resonant time through the co-extrusion setup 2. The coat hanger 35 is tapered where a proximal end connected to the coat hanger neck 33 is of greater axial length than its distal end. The capstock exits the coat hanger 35 and enters the capstock flow chamber 46 which is between the co-extrusion pin 34 and dual coex bushing 36. The capstock flow is restricted in the portion of the capstock flow chamber 46 connected to the proximal end of the coat hanger 35 to permit the capstock to flow symmetrically around the co-extrusion pin 34 reducing resonant time through the dual coex bushing 36. The solid substrate flows through the co-extrusion pin 34 at the same time the capstock flows around the co-extrusion pin 34. The capstock is applied to the exterior wall of the solid substrate at a distal end of the co-extrusion pin 34 and dual coex bushing 36. In other embodiments, the capstock can be applied to the interior of the solid substrate or to both the interior and exterior of the solid substrate.

Application of the capstock to the solid substrate before entering either the spider pipe head 8 or die 10 maintains uniform equilibrium pressure. The application of the capstock to a solid substrate results in an insignificant pressure drop because it occurs at a consistent high pressure of at least 1500 psi resulting in the CCS exiting the die at the same velocity.

The newly formed CCS then flows either into a spider pipe head or extrusion die. The spider pipe head 8 transforms the solid CCS into tubular form. The CCS enters the die 10 which further adjusts the shape of the extrusion. If a solid shape is preferred, the spider pipe head 8 may be removed from the co-extrusion setup 2.

The plate-to-block adapter 28 is aligned on the dual coex block 30 using alignment pins 54 and alignment holes 56. The plate-to-block adapter 28 is then bolted to the dual coex block 30 creating the capstock flow director. The vertical plate 26 is seated in and bolted to the plate-to-block adapter 28. The horizontal plate 24 seated in and bolted to the vertical plate 26. The adapter flange 22 bolts to the horizontal plate 24 and the capstock insert 20 is seated in the adapter flange 22. The capstock insert 20 transitions the capstock flow from the co-extruder to the co-extrusion assembly 6. A locating insert 32 is fitted between the dual coex block 30 and co-extrusion pin 34 to ensure proper alignment of the co-extrusion pin 34 and the dual coex block 30. The co-extrusion pin is bolted to the dual coex block 30. The dual coex bushing 36 is seated over the co-extrusion pin 34 and bolted to the dual coex block 30. The dual coex bushing can further be coupled to a spider pipe head 8 or extrusion die 10. A main flow insert 38 is seated in the dual coex block 30 and transitions the main flow from the "Y" adapter 4 to the dual coex block 30.

Heat plates 40 and heat bands 42 are attached to the horizontal plate 24, vertical plate 26, dual coex block 30 and dual coex bushing 36 to maintain stable temperature of the capstock, solid substrate and CCS resulting in a consistent viscosity. The heat plates 40 are covered by heat plate covers 50. The heat plates 40 and heat bands 42 can be individually controlled to adjust viscosity of the flowing melt. Thermocouple holders

[illegible][illegible]